
### TECHNICAL SKILLS COURSE 02 ANALYZING THE EFFECT OF CHANGES IN NEHOIU CATCHMENT



#### **Objectives**

•Classification and mapping buildings types

• Reconstructing flash flood event 2004

• Changes in damage of the elements at risk

### Analyzing And Mapping Buildings Type

#### **BUILDINGS ATTRIBUTE:**

- •occupancy type
- structural type
- flood area (width x length)
- nr floors
- floors space
- nr households
- remarks





### **Building samples**


Occupancy	Nr_Buildings	Wood	Adobe	Wood + Adobe	Wood+Stone Masonry	RCC + Masonry	Steel
Residential	26	16	1	8		1	
Commercial	11	5		5		1	
Storage	6	6					
Abandoned	2				1		1
Shed	2	2					
Touristic Hotel	1					1	
Restaurant	2	1				2	
Wood							
Workshop	1	1					
Community							
Center	1					1	
School	1					1	

#### Building sampling (cont.)

	id	occupancy_type	stru	ctural_type	nr_floors	remarks
1.	140010 residencial single house la		adobe		1	asbestos_roof
	140919 residencial _single house_lc					garage_storage_workshop
	140920 storage 140921 storage		wood			garage_storage_workshop
		storage	wood			garage_storage_workshop
1	40922	storage	wood		1	garage_storage_workshop
1	140923 residencial _single house_lc		wood_adobe		1	
1	140924 residencial _single house_lc		wood_adobe		3	
1	140925 residencial _single house_lc		wood_adobe		1	
1	140926 residencial _single house_lc		wood_ad	obe	2	
1	140927 storage_workshop		wood_fra	me_congl_wall	1	
1	140928 residencial_single_house_mo		wood		3	toopfloor_wood
1	140020		wood ad	oho	1	exsisting_building_corrugated_roof
	140929 residencial_single_lmc		wood_adobe wood			exsisting_building_corrugated_roor
	140930 residencial_single_lmc		wood			tenfloor attic
1	4097	29 residencial_single_l	mc	wood_adob	e	1 exsisting_building_corrugated_roof
1	.409	30 residencial_single_l	mç	wood		2 topfloor_attic
1	40935	residencial_single_lmc	wood		2	AND DESCRIPTION OF THE PARTY OF
1	40936	residencial_single_lc	wood_ste	e_sheet_roof	1	conglomerate_of_houses
1	140937 residencial_single_lc		wood_stee_sheet_roof		2	conglomerate_of_houses
1	140938 residencial_single_lc		wood_stee_sheet_roof		3	conglomerate_of_houses
1	140939 Residencial_single_lc		Wood_stee_sheet_roof		4	Conglomerate_of_houses
1	140940 Shop		Wood_stee_sheet_roof		1	Conglomerate_of_houses
1	140941 Shop		Wood		1	Second_hand_store


#### Reconstructing Flash Flood Event 2004

- Water height marks on poles and buildings
- River channel morphology
- Sediment load and debris along river channel
- Remains of damaged bridges




### What was the extension of the 2004 Flash Flood Event?





- Maximum height = 6 7 m
- Maximum extent = 120 m
- Road length = 4.5 km

### How many buildings are close to the river?




Distance	Number of building				
0 to 5 m	11				
5 to 10 m	10				
10 to 15 m	24				
15 to 20 m	23				
20 to 25 m	40				


### How many bridges were damaged?

BRIDGES		TYPE OF MATERIAL					
		CONCRETE METAL		WOOD	TOTAL		
DAMAGE	YES	4	2	1	7		
DAIVIAGE	NO	4	1	0	5		
	TOTAL	8	3	S	11		






### How many buildings are in the zone in which constructions were prohibited?



- 131 buildings are located in the zone that was indicated as a noconstruction zone after the 2004 event.
- Several new constructions are taking place



## How many buildings would be flooded if the 2004 event would happen now?



- 42 buildings are located in the zone that was flooded in the 2004 event.
- Some areas seem not to have been flooded at all.



# Thank you for your attention!